

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

KC1400
NNW
> 1
1.764 mi.
9312 ft.

TRANSFORMER MOAT
83RD ST/BAY PKWY
BROOKLYN, NY

NY Spills S102663530
N/A

Site 2 of 3 in cluster KC

Relative:
Higher

Actual:
19 ft.

SPILLS:

Name: TRANSFORMER MOAT
Address: 83RD ST/BAY PKWY
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9706279 / 2003-02-24
Facility ID: 9706279
Facility Type: ER
DER Facility ID: 155636
Site ID: 186153
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 1997-08-23
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1997-08-23
CID: 312
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1997-08-23
Spill Record Last Update: 2003-11-12
Spiller Name: Not reported
Spiller Company: CON EDISON
Spiller Address: 128 WEST END AVENUE
Spiller Company: 001
Contact Name: Not reported
DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was
ENGELHARDT e2mis 110741 8-23-97 0230 HRS G.RICHIE 21683 OS SERV BUR
REPORTS ON FDR.7B50 OA IN TM908 C/O 83 ST 38' W/O BAY PARKWAY HE
FOUND THE TRANSF BLEW SETTING 4 CARS ON FIRE AND OIL WAS BLOWN OUT
ONTO STREET AND SIDEWALK (PCB COUNT < 10 PPM). AT 0355 HRS
S.ZALLOUGH REPORTS OIL WENT INTO 3 SEWERS. CIG CESARE WAS NOTIFIED
AT 0356 HRS. CLEAN HARBORS WAS CALLED AT 0357 HRS AND REQUESTED CREW
FOR CLEANUP. MR.PAUL FEENEY REPORTS IT WILL TAKE 2 1/2 HRS FOR CREWS
TO REACH LOCATION. UPDATE 0443 HRS DEP KIM CALLED AND WOULD LIKE A
HARD COPY FAXED TO 1-718-595-4096. FAXED COPY 0445 HRS 8/23/97 06:00
ENV. ZALLOUGH REPORTS THAT OIL FROM THE TRANSFORMER MAY HAVE
CONTAMINATED THE FRONT LAWN @ 8320 BAY PKWY. CLEAN HARBORS TO REMOVE
DIRT FROM AFFECTED AREA. A TREE AT THE SAME LOC. ALSO WAS
CONTAMINATED WITH THE OIL AND WILL BE TRIMMED. CONST. CREWS AND
TANKER WERE DISPATCHED TO LOC. TO DRAIN ANY REMAINING OIL IN THE
TRANSFORMER. 08/23/97 08:20 ZALLOUGH REPORTS EST #04149 WAS PLACED
IN TM908. THE RESIDENT AT 8320 BAY PKWY. GAVE PERMISSION TO CLEAN
HARBORS TO REMOVE THE AFFECTED AREA OF HIS LAWN. ENERGY SERVICES
PICCARILLO IS ON LOCATION SPEAKING TO CONSUMERS. CLEAN HARBORS WASHED
2 VEHICLES LIC #R10-532 WHICH WAS TOWED TO APPLE TOWING FACILITY &

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Remarks:

G77TA WAS WASHED AND RETURNED TO THE OWNER. 8/23/97 14:55 ZALLOUGH
REPORTS TRANSFORMER WAS REMOVED, THAT CLEAN HARBORS HAS COMPLETED THE
CLEANUP OF 3 CATCH BASINS, THE STREET AREA AND HAS REMOVED AN AREA OF
DIRT 45'X10'X5 FROM THE LAWN OF 8320 BAY PKWY AND THAT #9 TSHV
OFTENDAHL REMOVED THE CONTAMINATED TREE LIMBS FROM 8224 BAY PKWY. THE
DEP WAS NOTIFIED OF THE PCB COUNT AND WAS APPRISED OF THE WAY THE JOB
WAS BEING WORKED AND DID NOT VISIT THE WORK SITE. UPDATE 8-26-97 2310
HRS A.HOWELL REPORTS AT TM908 HE FOUND OIL MIXED WITH WATER. THERE
ALSO WAS ROCKS IN HOLE SO THAT FLUSH TRUCK WAS UNABLE TO SUCK. NEED
TO HAVE A MEET WITH C&M AND A LESS THAN 50 PPM TANKER. JOB IS
INCOMPLETE AT THIS TIME. UPDATE*****K.HUFFORD REPORTS 10PPM
CLEAN UP cOMPLETED, LARGE DEBRIS LEFT IN MH. DEBRIS CLEANED & NO
TRACE OF OIL. THIS INCIDENT IS CLOSED "
"TRANSFORMER FAULTED CAUSING FIRE - FDNY EXTINGUISHED FIRE BY USING
WATER AND FOAM WHICH WAS THEN FLUSHED DOWN SEWERS - LESS THAN 10 PPM
FOR PCB'S - CLEAN HARBORS ENROUTE SHORTLY"

All Materials:

Site ID: 186153
Operable Unit ID: 1052431
Operable Unit: 01
Material ID: 331869
Material Code: 0020A
Material Name: transformer oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported